













The pictures show the effects of 1910 flood. Close to Terme Belliazzi arrived incredibles stones with a size more than 10 meter cube.

The reconstruction occurred during the first three decades of the 20th century provided an important set of infrastructures in order to mitigate the hydrogeological risk. Weir, terracing with mansory wall, riverbank protection





